BUILDING SAFETY CERTIFIACTE

No. 5084

Date: - 23 / 12 / 2022

- Structural stability should be examined also with reference to location, altitude, intensity
 of wind, flood.
- 2) Fire safety Inspection / report should be done by agency separately.
- 3) Minor hair cracks found on two outer site coloum should be repaired by agency/institute

Issued on 23/12/2022 at Nagpur by.

Strike out whichever is not applicable:

Sub-Division Engineer

Public Works Sub – Division (Rural) Nagpur

Signature wit Seal :

Exeguire Engineer

Name : Chandrshekhar I. Girling No.

Designation: Executive Engineer

Name of Address of Department Office: Public Works Division No. 2, Nagpur.

(Assistant Engineer & above officer of concerned Govt. Department only.)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only.

• The filled up certificate should be either In Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with

the original vernacular certificate as a single pdf.

ncipal condiner stienal School audo, unaguer

Spruke Ke